

Adding Acra-Plant Chrome Carbide Components to your existing equipment will yield additional acres of wear life and reduced downtime. Use Weld-On Points to repair worn parts or build your own custom tools.

OEM Replacement Pin-on Cultivator Points

Part #	Description	Weight
TF-102	Krause 4600 row crop cultivator pin-on point • Designed for 1" shank Krause cultivators	2.00

Part #	Description	Weight
TF-130N	Orthman 164-043 point • Improved for 2005 with Chisel Nose to enhance penetration and wear life • Casting # TF130 or TF 130N	2.85



TF-102



TF-130N

See SECTION 4 of this catalog for all of our chrome carbide ripper & subsoiler points

Weld-On Cultivator, Sweep, Chisel Plow & Lister Points

Use 7018 welding rod or Low Hydrogen Wire to weld these parts. Consult factory for details.

Part #	Description	Weight
TFN-1001	Field cultivator point, 3" long with step-pocket underside to weld onto cultivator points and small sweeps	0.23

Part #	Description	Weight
TFEDP-60C	Field cultivator diamond point, 3-1/2" long with flat bottom to weld onto top of cultivator points or shanks	0.41

Part #	Description	Weight
TTFN-1002	Sweep point, open top, 3" long with step-pocket top side to weld onto any standard cultivator, chisel plow or Fallowmaster sweep	0.29



TFN-1001



TFEDP-60C



TTFN-1002

Special Application



Made in the USA

Weld-On Cultivator, Sweep, Chisel Plow & Lister Points

Use 7018 welding rod or Low Hydrogen Wire to weld these parts. Consult factory for details.



TFN-1005

Part #	Description	Weight
TFN-1005	Chisel spike point, 3-1/2" long x 2" wide <ul style="list-style-type: none"> Designed to weld on 2" spikes, pocket underside to weld onto the end of chisel spike Casting # TFN1005 	0.73



TFN-1006

Part #	Description	Weight
TFN-1006	Heavy-duty chisel point, 4-3/4" long x 3" wide <ul style="list-style-type: none"> Designed to weld on 3" twisted chisels, pocket underside to weld onto the end of chisel or fabricated spike Casting # TFN1006 	1.04



TFN-1007

Part #	Description	Weight
TFN-1007	Heavy-duty sweep or chisel point, open top, 3-1/2" long with 1/2" deep step-pocket top side to weld onto chisel plow sweeps or repair 2" wide chisels	0.69



TFN-1010

Part #	Description	Weight
TFN-1010	Big Lister Point, 6" long x 4-1/2" wide, hollow pocket <ul style="list-style-type: none"> Underside to weld onto nose section of 3-piece listers Casting # TFN1010 	1.63

**Cultivators, Sweeps, Chisel Plows or Listers —
Acra-Plant has solid chrome carbide points to help
you improve performance and add wear life for the
"Do-It-Yourself" farmer.**



Made in the USA